





Packard cable standard



Color	4..20mA two wires sensor	0,5..4,5V three wires sensor
Blue (B)	+V (supply)	+5V (supply)
Brown (C)	out signal	out signal
White (A)	/	0V/Gnd

Standard Codes	L (m)
A000013420	2
A000013423	5

Packard cable with shield



Packard cable with shield

Color	4..20mA two wires sensor	0,5..4,5V three wires sensor
Black (B)	+V (supply)	+5V (supply)
White (C)	out signal	out signal
Green (A)	/	0V/Gnd

Standard Codes	L (m)
A000013427	5
A000013428	12
A000013429	18